
Oct 24 2019 09:02:16-AM

VIN retrieved from vehicle

VIN: 1FAFP44483F305022

Vehicle: 2003 Ford Mustang

0 Confirmed Trouble Codes:

0 Pending Trouble Codes:

1 Powertrain Control Module Trouble Codes:

- P1000: On-Board Diagnostic (OBD) Systems Readiness Test Not Complete
-

1 Instrument Cluster Trouble Codes:

- C1284: Oil Pressure Switch Failure\nNote: This code may not be valid. Re-run the Self-Test with the vehicle running to verify the code.
-

Vehicle Protocol: J1850_PWM

Sensor F/W Version: v2.44

App Version: 6.12.2-b201

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.