




# TurboStang



## After EFI



## Boost Stock Base startup map



After EFI / IGN increased did not run that much better

170.0	22.0	22.0	22.0	22.0	25.1	19.1	21.1	22.1	22.1	22.1	22.1	22.1	22.1	22.1
150.0	22.0	22.0	22.0	22.0	22.1	19.1	21.1	22.1	22.1	22.1	22.1	22.1	22.1	22.1
140.0	25.2	22.0	22.0	22.0	22.1	19.1	21.1	22.1	22.1	22.1	22.1	22.1	22.1	22.1
130.0	25.0	25.0	25.0	25.0	22.1	19.1	21.1	22.1	22.1	22.1	22.1	22.1	22.1	22.1
115.0	25.0	25.0	25.0	25.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0
100.0	25.0	25.0	25.0	30.5	28.7	26.8	25.0	24.0	24.0	24.0	24.0	24.0	24.0	24.0
85.0	25.0	25.0	25.0	30.0	33.0	36.0	36.0	34.5	33.0	33.0	33.0	33.0	33.0	33.0
70.0	25.0	25.0	25.0	30.0	33.0	36.0	36.0	34.5	33.0	33.0	33.0	33.0	33.0	33.0
50.0	25.0	25.0	25.0	30.0	33.0	36.0	36.0	34.5	33.0	33.0	33.0	33.0	33.0	33.0
30.0	25.0	25.0	25.0	30.0	33.0	36.0	36.0	34.5	33.0	33.0	33.0	33.0	33.0	33.0
40.0	25.0	25.0	25.0	30.0	33.0	36.0	36.0	34.5	33.0	33.0	33.0	33.0	33.0	33.0
30.0	22.0	25.0	25.0	30.0	33.0	36.0	36.0	34.5	33.0	33.0	33.0	33.0	33.0	33.0
↳	701	1000	1500	2000	2500	3000	3500	4000	4500	5000	6000	6500		

rpm

### Pay Forward Timing

Timing Table - Building one for Boost [Pay it Forward Garage EP3]

260.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	12.0	
233.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	13.0	
206.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	14.0	
180.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	16.0	
153.0	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	18.5	
127.0	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	20.2	
100.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	22.0	
90.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	26.0	
80.0	22.0	22.0	22.0	30.0	30.0	30.0	30.0	28.0	28.0	28.0	28.0	28.0	28.0	28.0	28.0	
70.0	22.0	22.0	22.0	32.0	32.0	32.0	30.0	30.0	28.0	28.0	28.0	28.0	28.0	28.0	28.0	
60.0	22.0	22.0	22.0	33.0	33.0	33.0	30.0	30.0	28.0	28.0	28.0	28.0	28.0	28.0	28.0	
50.0	22.0	22.0	22.0	35.0	35.0	35.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	30.0	
40.0	22.0	22.0	22.0	35.0	35.0	35.0	35.0	32.0	32.0	33.0	33.0	33.0	33.0	33.0	33.0	
30.0	26.0	22.0	22.0	26.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	
25.0	26.0	22.0	22.0	26.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	
15.0	26.0	22.0	22.0	26.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	38.0	
↳	500	700	900	1300	1700	2200	2800	3500	4000	4500	5000	5500	6000	6500	6850	7200

rpm