

MANUFACTURER	WEB SITE	FLAGS	COST	Power or Manual	EASE OF INSTALL	TURN RADIUS	LOCK TO LOCK	COMPETE KIT?	BUMPSTEER	FLEX	WARRANTY	COLUMN CHANGE	OTHER
Randall's Rack	www.randallsrack.com	May not fit '69	\$1395 - \$1695w/pump	Power	Bolt in, may have to modify column		3 turns			One piece crossmember - "Beefy" per ZN6killinSBE		Keep original column	
TCP	www.totalcontrolproducts.com	Expensive, specific to engine size/type	\$1299+ Manual \$2000+ Power	Both Available	Bolt in		3 turns			One piece crossmember			
RRS	www.autoworksracing.com	May not fit long tube headers	\$2,095	Both Available	Have to drill holes in stock frame			Yes	Corrected for bumpsteer		Yes	Modify stock	Pump optional
Speed Direct	www.speeddirect.com	Flexes under load, short turn radius	\$1,150 - \$1,450w/column		Bolt in, modify column or replace					Flexes under load.		Optional, modify original	Stock steering wheel won't fit
Flaming River													
Dynamic Racing	www.dynamicracingproducts.com	Crossmember looks flimsy, questionable header clearance	\$899 on Ebay, \$989 at web site	Manual	Bolt in		3.75 lock to lock, 18:1	Seller states it is complete		Crossmember looks flimsy		Modify original?	
Stock Power		Sloppy!		Power	N/A		3.75 turns	N/A	N/A	N/A	N/A	N/A	N/A
Stock Manual		Sloppy!		Manual	N/A		4.63 turns	N/A	N/A	N/A	N/A	N/A	N/A